

SERIAL NO.: 09/706,579 DOCKET NO.: 279.271US1

REPLACEMENT SHEET





Fig.4






Fig.6




Fig.8A




Fig.7





Fig.8B

TITLE: CAPACITOR HAVING A FEEDTHROUGH ASSEMBLY WITH A COUPLING MEMBER

INVENTOR'S NAME: MICHAEL J. O'PHELAN, ET AL. SERIAL NO.: 09/706,579 DOCKET NO.: 279.271US1

REPLACEMENT SHEET

3/5






Fig.10

INVENTOR'S NAME: MICHAEL J. O'PHELAN, ET AL. SERIAL NO.: 09/706,579 DOCKET NO.: 279.271US1

REPLACEMENT SHEET

4/5




Fig.11




Fig.12

TITLE: CAPACITOR HAVING A FEEDTHROUGH ASSEMBLY WITH A COUPLING MEMBER INVENTOR'S NAME: MICHAEL J. O'PHELAN, ET AL.

SERIAL NO.: 09/706,579 DOCKET NO.: 279.271US1

PEDI ACEI

5/5

REPLACEMENT SHEET




Fig.13